

FORM CQA/CF/09H

2 August 2011
Job No. CQA/10/370

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4000

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 118 - WARNER
REAL PROPERTY DESCRIPTION:
LOT NO. 100 ON SP216672, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 1350

Fill was placed on this lot during the construction of this estate.

Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/10/370 dated 02/08/11 and in CQA Report, Job No. CQA/10/099 dated 20/10/10.


Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 1350 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, within the time frame of our inspection and testing programme between 08/04/10 – 14/07/10 and 28/01/11 – 13/07/11 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty Ltd. on 3881 3511.


A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L


PG FRASER
RPEQ No. 7476
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L

Enc. Drawing showing lateral extent of controlled filling
ab4856mhb.docx



**CIVIL
QUALITY
ASSURANCE
(QLD) PTY LTD**
ABN 52 058 855 431

GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON - HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LAIDLEY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
laidley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09H

2 August 2011
Job No. CQA/10/370

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4000

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 118 - WARNER
REAL PROPERTY DESCRIPTION:
LOT NO. 100 ON SP216672, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 1351

Fill was placed on this lot during the construction of this estate.

Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/10/370 dated 02/08/11 and in CQA Report, Job No. CQA/10/099 dated 20/10/10.


Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 1351 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, within the time frame of our inspection and testing programme between 08/04/10 – 14/07/10 and 28/01/11 – 13/07/11 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty. Ltd. on 3881 3511.


A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L


PG FRASER
RPEQ No. 7476
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L

Enc. Drawing showing lateral extent of controlled filling
ab4856mhb.docx



**CIVIL
QUALITY
ASSURANCE
(QLD) PTY LTD**
ABN 52 058 855 431

GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON - HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LAIDLEY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
laidley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09H

2 August 2011
Job No. CQA/10/370

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4000

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 118 - WARNER
REAL PROPERTY DESCRIPTION:
LOT NO. 100 ON SP216672, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 1352

Fill was placed on this lot during the construction of this estate.

Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/10/370 dated 02/08/11 and in CQA Report, Job No. CQA/10/099 dated 20/10/10.


Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 1352 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, within the time frame of our inspection and testing programme between 08/04/10 – 14/07/10 and 28/01/11 – 13/07/11 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty Ltd. on 3881 3511.


A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L


PG FRASER
RPEQ No. 7476
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L

Enc. Drawing showing lateral extent of controlled filling
ab4856mhb.docx



**CIVIL
QUALITY
ASSURANCE
(QLD) PTY LTD**
ABN 52 058 855 431

GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON - HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LAIDLEY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
laidley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09H

2 August 2011
Job No. CQA/10/370

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4000

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 118 - WARNER
REAL PROPERTY DESCRIPTION:
LOT NO. 100 ON SP216672, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 1353

Fill was placed on this lot during the construction of this estate.


Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/10/370 dated 02/08/11 and in CQA Report, Job No. CQA/10/099 dated 20/10/10.

Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 1353 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, within the time frame of our inspection and testing programme between 08/04/10 – 14/07/10 and 28/01/11 – 13/07/11 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty. Ltd. on 3881 3511.



A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L



PG FRASER
RPEQ No. 7476
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L

Enc. Drawing showing lateral extent of controlled filling
ab4856mhb.docx



**CIVIL
QUALITY
ASSURANCE
(QLD) PTY LTD**
ABN 52 058 855 431

GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON – HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LAIDLEY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
laidley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09H

2 August 2011
Job No. CQA/10/370

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4000

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 118 - WARNER
REAL PROPERTY DESCRIPTION:
LOT NO. 100 ON SP216672, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 1354

Fill was placed on this lot during the construction of this estate.

Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/10/370 dated 02/08/11 and in CQA Report, Job No. CQA/10/099 dated 20/10/10.


Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 1354 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, within the time frame of our inspection and testing programme between 08/04/10 – 14/07/10 and 28/01/11 – 13/07/11 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty Ltd. on 3881 3511.


A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L


PG FRASER
RPEQ No. 7476
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L

Enc. Drawing showing lateral extent of controlled filling
ab4856mhb.docx



**CIVIL
QUALITY
ASSURANCE
(QLD) PTY LTD**
ABN 52 058 865 431

GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS

ALL CORRESPONDENCE TO
PO BOX 370
LAWNTON, QLD, 4501

LAWNTON - HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LAIDLEY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
laidley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09H

2 August 2011
Job No. CQA/10/370

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4000

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 118 - WARNER
REAL PROPERTY DESCRIPTION:
LOT NO. 100 ON SP216672, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 1355

Fill was placed on this lot during the construction of this estate.

Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/10/370 dated 02/08/11 and in CQA Report, Job No. CQA/10/099 dated 20/10/10.


Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 1355 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, within the time frame of our inspection and testing programme between 08/04/10 – 14/07/10 and 28/01/11 – 13/07/11 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty. Ltd on 3881 3511.


A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L


PG FRASER
RPEQ No. 7476
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L

Enc. Drawing showing lateral extent of controlled filling
ab4856mhb.docx



**CIVIL
QUALITY
ASSURANCE
(QLD) PTY LTD**
ABN 52 058 865 431

GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON – HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LAIDLIEY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
laidley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09H

2 August 2011
Job No. CQA/10/370

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4000

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 118 - WARNER
REAL PROPERTY DESCRIPTION:
LOT NO. 100 ON SP216672, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 1356

Fill was placed on this lot during the construction of this estate.

Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/10/370 dated 02/08/11 and in CQA Report, Job No. CQA/10/099 dated 20/10/10.


Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 1356 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, within the time frame of our inspection and testing programme between 08/04/10 – 14/07/10 and 28/01/11 – 13/07/11 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty Ltd. on 3881 3511.


A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L


PG FRASER
RPEQ No. 7476
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L

Enc. Drawing showing lateral extent of controlled filling
ab4856mhb.docx



**CIVIL
QUALITY
ASSURANCE
(QLD) PTY LTD**
ABN 52 058 855 431

GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON - HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LADLEY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
ladley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09H

2 August 2011
Job No. CQA/10/370

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4000

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 118 - WARNER
REAL PROPERTY DESCRIPTION:
LOT NO. 100 ON SP216672, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 1357

Fill was placed on this lot during the construction of this estate.

Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/10/370 dated 02/08/11 and in CQA Report, Job No. CQA/10/099 dated 20/10/10.


Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 1357 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, within the time frame of our inspection and testing programme between 08/04/10 – 14/07/10 and 28/01/11 – 13/07/11 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty Ltd. on 3881 3511.


A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L


PG FRASER
RPEQ No. 7476
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L

Enc. Drawing showing lateral extent of controlled filling
ab4856mhb.docx



**CIVIL
QUALITY
ASSURANCE
(QLD) PTY LTD**
ABN 52 058 855 431

GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON - HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LAIDLAY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
laidley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09H

2 August 2011
Job No. CQA/10/370

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4000

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 118 - WARNER
REAL PROPERTY DESCRIPTION:
LOT NO. 100 ON SP216672, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 1358

Fill was placed on this lot during the construction of this estate.

Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/10/370 dated 02/08/11 and in CQA Report, Job No. CQA/10/099 dated 20/10/10.


Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 1358 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, within the time frame of our inspection and testing programme between 08/04/10 – 14/07/10 and 28/01/11 – 13/07/11 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty. Ltd. on 3881 3511.


A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L


PG FRASER
RPEQ No. 7476
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L

Enc. Drawing showing lateral extent of controlled filling
ab4856mhb.docx



**CIVIL
QUALITY
ASSURANCE
(QLD) PTY LTD**
ABN 52 058 855 431

GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON - HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LIDLAY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
laidley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09H

2 August 2011
Job No. CQA/10/370

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4000

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 118 - WARNER
REAL PROPERTY DESCRIPTION:
LOT NO. 100 ON SP216672, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 1359

Fill was placed on this lot during the construction of this estate.

Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/10/370 dated 02/08/11 and in CQA Report, Job No. CQA/10/099 dated 20/10/10.


Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 1359 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, within the time frame of our inspection and testing programme between 08/04/10 – 14/07/10 and 28/01/11 – 13/07/11 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty. Ltd on 3881 3511.


A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L


PG FRASER
RPEQ No. 7476
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L

Enc. Drawing showing lateral extent of controlled filling
ab4856mhb.docx



**CIVIL
QUALITY
ASSURANCE
(QLD) PTY LTD**
ABN 52 058 855 431

GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON - HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LAILY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
laily@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09H

2 August 2011
Job No. CQA/10/370

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4000

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 118 - WARNER
REAL PROPERTY DESCRIPTION:
LOT NO. 100 ON SP216672, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 1360

Fill was placed on this lot during the construction of this estate.

Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/10/370 dated 02/08/11 and in CQA Report, Job No. CQA/10/099 dated 20/10/10.


Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 1360 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, within the time frame of our inspection and testing programme between 08/04/10 – 14/07/10 and 28/01/11 – 13/07/11 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty Ltd. on 3881 3511.


A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L


PG FRASER
RPEQ No. 7476
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L

Enc. Drawing showing lateral extent of controlled filling
ab4856mhb.docx



**CIVIL
QUALITY
ASSURANCE
(QLD) PTY LTD**
ABN 52 058 865 431

GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON - HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1635
kunda@cqa.com.au

LIDLAY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
laidley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09H

2 August 2011
Job No. CQA/10/370

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4000

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 118 - WARNER
REAL PROPERTY DESCRIPTION:
LOT NO. 100 ON SP216672, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 1361

Fill was placed on this lot during the construction of this estate.


Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/10/370 dated 02/08/11 and in CQA Report, Job No. CQA/10/099 dated 20/10/10.


Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 1361 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, within the time frame of our inspection and testing programme between 08/04/10 – 14/07/10 and 28/01/11 – 13/07/11 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.


Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty. Ltd. on 3881 3511.


A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L


PG FRASER
RPEQ No. 7476
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L

Enc. Drawing showing lateral extent of controlled filling
ab4856mhb.docx



**CIVIL
QUALITY
ASSURANCE
(QLD) PTY LTD**
ABN 52 058 855 431

GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON – HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LAIDLAY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
laidley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09H

2 August 2011
Job No. CQA/10/370

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4000

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 118 - WARNER
REAL PROPERTY DESCRIPTION:
LOT NO. 100 ON SP216672, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 1362

Fill was placed on this lot during the construction of this estate.

Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/10/370 dated 02/08/11 and in CQA Report, Job No. CQA/10/099 dated 20/10/10.


Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 1362 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, within the time frame of our inspection and testing programme between 08/04/10 – 14/07/10 and 28/01/11 – 13/07/11 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty. Ltd. on 3881 3511.


A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L


PG FRASER
RPEQ No. 7476
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L

Enc. Drawing showing lateral extent of controlled filling
ab4856mhb.docx



**CIVIL
QUALITY
ASSURANCE**
(QLD) PTY LTD
ABN 52 058 855 431

GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON - HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LAIDLAY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
laidley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"