 Approximate lateral extent of Level 1 (controlled filling) area. Controlled fill certification is limited to within this area. Unless specifically stated in the report, level 1 compaction control and certification does not address or include:

- backfill to service trenches and/or retaining walls (including boulder walls); and
- topsoil placed subsequent to completion of controlled filling.

Note: Base Plan Supplied by  
Brown Consulting





CIVIL QUALITY ASSURANCE (QLD) PTY LTD  
GEOTECHNICAL AND ENVIRONMENTAL CONSULTANTS

Originating office:  
1/18 Leanne Crescent  
Lewinton QLD 4501  
Ph: (07) 3881 3511  
Fdx (07) 3881 3513


Also at:  
Loganholme and  
Sunshine Coast

JOB LOCATION		DRAWING NO.	
Warner Lakes Estate Stage 116 & 117 - Bulk Earthworks		CQA/09/291-D1	
CLIENT	SIZE	DATE	DRAWN
Brown Consulting	A3	07/01/10	AB
SCALE	SCALE NOT SHOWN		



 Approximate lateral extent of Level 1 (controlled filling).  
 Controlled fill certification is limited to within this area.  
 Unless specifically stated in the report, level 1 compaction control and certification does not address or include:  
 • backfill to service trenches and/or retaining walls (including boulder walls); and  
 • topsoil placed subsequent to completion of controlled filling.

Note: Base Plan Supplied by  
Brown Consulting



CIVIL QUALITY ASSURANCE  
 CIVIL QUALITY ASSURANCE (QLD) PTY LTD  
 GEOTECHNICAL AND ENVIRONMENTAL CONSULTANTS

Originating office:  
 1/18 Leanne Crescent  
 Lomton QLD 4501  
 Ph: (07) 3881 3511  
 Fax: (07) 3881 3513

Also of:  
 Logonholme and  
 Sunshine Coast

JOB LOCATION		Warner Lakes Estate Stage 116 & 117- Bulk Earthworks	
CLIENT	SCALE	DATE	DRAWING NO.
Brown Consulting	A3	07/01/10	CQA/09/291-D2
SCALE NOT SHOWN			DRAWN
			AB