
 Approximate lateral extent of Level 1 (controlled filling).
 Controlled fill certification is limited to within this area.
 Unless specifically stated in the report, level 1 compaction control and certification does not address or include:

- backfill to service trenches and/or retaining walls (including boulder walls); and
- topsoil placed subsequent to completion of controlled filling.



Note: Base Plan Supplied by Brown Consulting




CIVIL QUALITY ASSURANCE (QLD) PTY LTD
 GEOTECHNICAL AND ENVIRONMENTAL CONSULTANTS

Originating office:
 1/18 Leanne Crescent
 Lawnton QLD 4501
 Ph: (07) 3881 3511
 Fax (07) 3881 3513

Also at:
 Loganholme and
 Sunshine Coast

Warner Lakes Estate Stage 116 & 117- Bulk Earthworks

CLIENT	SIZE	DRAWING No
Brown Consulting	A3	CQA/09/291-D1
SCALE	DATE	DRAWN
SCALE NOT SHOWN	07/01/10	AB

 Approximate lateral extent of Level 1 (controlled filling).
 Controlled fill certification is limited to within this area.
 Unless specifically stated in the report, level 1 compaction control and certification does not address or include:

- backfill to service trenches and/or retaining walls (including boulder walls); and
- topsoil placed subsequent to completion of controlled filling.



Note: Base Plan Supplied by Brown Consulting




CIVIL QUALITY ASSURANCE (QLD) PTY LTD
 GEOTECHNICAL AND ENVIRONMENTAL CONSULTANTS


Originating office:
 1/18 Leanne Crescent
 Lawnton QLD 4501
 Ph: (07) 3881 3511
 Fax (07) 3881 3513

Also at:
 Loganholme and
 Sunshine Coast

JOB LOCATION		
Warner Lakes Estate Stage 116 & 117- Bulk Earthworks		
CLIENT	SIZE	DRAWING NO
Brown Consulting	A3	CQA/09/291-D2
SCALE	DATE	DRAWN
SCALE NOT SHOWN	07/01/10	AB

 Approximate lateral extent of Level 1 (controlled filling).
 Controlled fill certification is limited to within this area.
 Unless specifically stated in the report, level 1 compaction control and certification does not address or include:

- backfill to service trenches and/or retaining walls (including boulder walls); and
- topsoil placed subsequent to completion of controlled filling.



Note: Base Plan Supplied by Brown Consulting



CIVIL QUALITY ASSURANCE (QLD) PTY LTD
 GEOTECHNICAL AND ENVIRONMENTAL CONSULTANTS

Originating office:
 1/18 Leanne Crescent
 Lawnton QLD 4501
 Ph: (07) 3881 3511
 Fax: (07) 3881 3513

Also at:
 Loganholme and
 Sunshine Coast

JOB LOCATION		
Warner Lakes Estate Stage 116 & 117- Bulk Earthworks		
CLIENT	SIZE	DRAWING No
Brown Consulting	A3	CQA/09/291-D3
SCALE	DATE	DRAWN
SCALE NOT SHOWN	07/01/10	AB