

FORM CQA/CF/09G

25 September 2009
Job No. CQA/09/191

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4001

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 115 – BALANCE OF WORKS
REAL PROPERTY DESCRIPTION:
LOT NO. 904 ON SP206021, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 966

Fill was placed on this lot during the construction of this estate.

Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/09/191 dated 25/09/09.

Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 966 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, placed within the time frame of our inspection and testing programme between 23/02/09-18/05/09 and 26/06/09-20/08/09 is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty. Ltd. on 3881 3511.



**A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L**

Enc. Drawing showing lateral extent of controlled filling
ab3476mb



**CIVIL
QUALITY
ASSURANCE
(QLD) PTY LTD**
ABN 52 058 855 431

**GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS**

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON – HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LAILLEY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
lailley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09G

25 September 2009
Job No. CQA/09/191

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4001

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 115 – BALANCE OF WORKS
REAL PROPERTY DESCRIPTION:
LOT NO. 904 ON SP206021, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 967

Fill was placed on this lot during the construction of this estate.

Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/09/191 dated 25/09/09.

Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 967 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.


All fill in the areas defined in the attached drawing, placed within the time frame of our inspection and testing programme between 23/02/09-18/05/09 and 26/06/09-20/08/09 is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty. Ltd. on 3881 3511.


A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L

Enc. Drawing showing lateral extent of controlled filling
ab3476mb



**CIVIL
QUALITY
ASSURANCE
(QLD) PTY LTD**
ABN 52 058 855 431

GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON – HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LAILLEY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
lailley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09G

25 September 2009
Job No. CQA/09/191

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4001

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 115 – BALANCE OF WORKS
REAL PROPERTY DESCRIPTION:
LOT NO. 904 ON SP206021, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 968

Fill was placed on this lot during the construction of this estate.

Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/09/191 dated 25/09/09.

Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 968 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, placed within the time frame of our inspection and testing programme between 23/02/09-18/05/09 and 26/06/09-20/08/09 is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty. Ltd. on 3881 3511.



A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L

Enc. Drawing showing lateral extent of controlled filling
ab3476mb



**CIVIL
QUALITY
ASSURANCE**
(QLD) PTY LTD
ABN 52 088 865 431

GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON – HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LIDLAY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
laidley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09G

25 September 2009
Job No. CQA/09/191

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4001

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 115 – BALANCE OF WORKS
REAL PROPERTY DESCRIPTION:
LOT NO. 904 ON SP206021, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 969

Fill was placed on this lot during the construction of this estate.


Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/09/191 dated 25/09/09.

Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 969 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, placed within the time frame of our inspection and testing programme between 23/02/09-18/05/09 and 26/06/09-20/08/09 is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty. Ltd. on 3881 3511.


A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L

Enc. Drawing showing lateral extent of controlled filling
ab3476mb



**CIVIL
QUALITY
ASSURANCE
(QLD) PTY LTD**
ABN 52 058 855 431

GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON – HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LAIDLEY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
laidley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09G

25 September 2009
Job No. CQA/09/191

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4001

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 115 – BALANCE OF WORKS
REAL PROPERTY DESCRIPTION:
LOT NO. 904 ON SP206021, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 970

Fill was placed on this lot during the construction of this estate.

Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/09/191 dated 25/09/09.

Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 970 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, placed within the time frame of our inspection and testing programme between 23/02/09-18/05/09 and 26/06/09-20/08/09 is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.


Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty. Ltd. on 3881 3511.



A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L

Enc. Drawing showing lateral extent of controlled filling
ab3476mb



**CIVIL
QUALITY
ASSURANCE**
(QLD) PTY LTD
ABN 52 058 855 431

GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON – HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LAIDLEY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
laidley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09G

25 September 2009
Job No. CQA/09/191

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4001

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 115 – BALANCE OF WORKS
REAL PROPERTY DESCRIPTION:
LOT NO. 904 ON SP206021, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 971

Fill was placed on this lot during the construction of this estate.

Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/09/191 dated 25/09/09.

Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 971 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, placed within the time frame of our inspection and testing programme between 23/02/09-18/05/09 and 26/06/09-20/08/09 is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty. Ltd. on 3881 3511.



A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L

Enc. Drawing showing lateral extent of controlled filling
ab3476mb



**CIVIL
QUALITY
ASSURANCE**
(QLD) PTY LTD
ABN 52 058 855 431

GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON – HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LIDLAY OFFICE
43 VALUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
laidley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09G

25 September 2009
Job No. CQA/09/191

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4001

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 115 – BALANCE OF WORKS
REAL PROPERTY DESCRIPTION:
LOT NO. 904 ON SP206021, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 972

Fill was placed on this lot during the construction of this estate.

Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/09/191 dated 25/09/09.

Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 972 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, placed within the time frame of our inspection and testing programme between 23/02/09-18/05/09 and 26/06/09-20/08/09 is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty. Ltd. on 3881 3511.


A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L

Enc. Drawing showing lateral extent of controlled filling
ab3476mb



**CIVIL
QUALITY
ASSURANCE
(QLD) PTY LTD**
ABN 52 058 855 431

GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON – HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LAILLEY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
laidley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09G

25 September 2009
Job No. CQA/09/191

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4001

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 115 – BALANCE OF WORKS
REAL PROPERTY DESCRIPTION:
LOT NO. 904 ON SP206021, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 973

Fill was placed on this lot during the construction of this estate.

Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/09/191 dated 25/09/09.

Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 973 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, placed within the time frame of our inspection and testing programme between 23/02/09-18/05/09 and 26/06/09-20/08/09 is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty. Ltd. on 3881 3511.



A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L

Enc. Drawing showing lateral extent of controlled filling
ab3476mb



**CIVIL
QUALITY
ASSURANCE**
(QLD) PTY LTD
ABN 52 058 855 431

GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON – HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LAIDLEY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
laidley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09G

25 September 2009
Job No. CQA/09/191

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4001

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 115 – BALANCE OF WORKS
REAL PROPERTY DESCRIPTION:
LOT NO. 904 ON SP206021, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 974

Fill was placed on this lot during the construction of this estate.

Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/09/191 dated 25/09/09.

Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 974 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, placed within the time frame of our inspection and testing programme between 23/02/09-18/05/09 and 26/06/09-20/08/09 is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty. Ltd. on 3881 3511.



A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L

Enc. Drawing showing lateral extent of controlled filling
ab3476mb



**CIVIL
QUALITY
ASSURANCE
(QLD) PTY LTD**
ABN 52 058 855 431

GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON – HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LAIDLEY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
laidley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09G

25 September 2009
Job No. CQA/09/191

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4001

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 115 – BALANCE OF WORKS
REAL PROPERTY DESCRIPTION:
LOT NO. 904 ON SP206021, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 975

Fill was placed on this lot during the construction of this estate.

Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/09/191 dated 25/09/09.

Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 975 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, placed within the time frame of our inspection and testing programme between 23/02/09-18/05/09 and 26/06/09-20/08/09 is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty. Ltd. on 3881 3511.



A BARCLAY

for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L

Enc. Drawing showing lateral extent of controlled filling
ab3476mb



**CIVIL
QUALITY
ASSURANCE
(QLD) PTY LTD**
ABN 52 058 855 431

GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON – HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LAIDLEY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
laidley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09G

25 September 2009
Job No. CQA/09/191

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4001

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 115 – BALANCE OF WORKS
REAL PROPERTY DESCRIPTION:
LOT NO. 904 ON SP206021, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 976

Fill was placed on this lot during the construction of this estate.

Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/09/191 dated 25/09/09.

Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 976 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, placed within the time frame of our inspection and testing programme between 23/02/09-18/05/09 and 26/06/09-20/08/09 is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty. Ltd. on 3881 3511.



A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L

Enc. Drawing showing lateral extent of controlled filling
ab3476mb



**CIVIL
QUALITY
ASSURANCE**
(QLD) PTY LTD
ABN 52 058 855 431

GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON – HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LADLEY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
ladley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09G

25 September 2009
Job No. CQA/09/191

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4001

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 115 – BALANCE OF WORKS
REAL PROPERTY DESCRIPTION:
LOT NO. 904 ON SP206021, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 1124

Fill was placed on this lot during the construction of this estate.

Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/09/191 dated 25/09/09.

Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 1124 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, placed within the time frame of our inspection and testing programme between 23/02/09-18/05/09 and 26/06/09-20/08/09 is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty. Ltd. on 3881 3511.



A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L

Enc. Drawing showing lateral extent of controlled filling
ab3476mb



**CIVIL
QUALITY
ASSURANCE**
(QLD) PTY LTD
ABN 52 058 865 431

GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON – HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LAIDLEY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
laidley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09G

25 September 2009
Job No. CQA/09/191

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4001

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 115 – BALANCE OF WORKS
REAL PROPERTY DESCRIPTION:
LOT NO. 904 ON SP206021, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 1125

Fill was placed on this lot during the construction of this estate.

Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/09/191 dated 25/09/09.

Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 1125 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, placed within the time frame of our inspection and testing programme between 23/02/09-18/05/09 and 26/06/09-20/08/09 is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty. Ltd. on 3881 3511.



A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L

Enc. Drawing showing lateral extent of controlled filling
ab3476mb



**CIVIL
QUALITY
ASSURANCE
(QLD) PTY LTD**
ABN 52 058 855 431

GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON – HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LIDLAY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
laidley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09G

25 September 2009
Job No. CQA/09/191

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4001

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 115 – BALANCE OF WORKS
REAL PROPERTY DESCRIPTION:
LOT NO. 904 ON SP206021, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 1126

Fill was placed on this lot during the construction of this estate.


Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/09/191 dated 25/09/09.

Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 1126 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, placed within the time frame of our inspection and testing programme between 23/02/09-18/05/09 and 26/06/09-20/08/09 is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty. Ltd. on 3881 3511.


A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L

Enc. Drawing showing lateral extent of controlled filling
ab3476mb



**CIVIL
QUALITY
ASSURANCE
(QLD) PTY LTD**

ABN 52 056 855 431

GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON – HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LAIDLEY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
laidley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09G

25 September 2009
Job No. CQA/09/191

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4001

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 115 – BALANCE OF WORKS
REAL PROPERTY DESCRIPTION:
LOT NO. 904 ON SP206021, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 1127

Fill was placed on this lot during the construction of this estate.

Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/09/191 dated 25/09/09.

Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 1127 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, placed within the time frame of our inspection and testing programme between 23/02/09-18/05/09 and 26/06/09-20/08/09 is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty. Ltd. on 3881 3511.



A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L

Enc. Drawing showing lateral extent of controlled filling
ab3476mb



**CIVIL
QUALITY
ASSURANCE
(QLD) PTY LTD**
ABN 52 058 855 431

GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON – HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LADLEY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
ladley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09G

25 September 2009
Job No. CQA/09/191

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4001

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 115 – BALANCE OF WORKS
REAL PROPERTY DESCRIPTION:
LOT NO. 904 ON SP206021, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 1128

Fill was placed on this lot during the construction of this estate.

Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/09/191 dated 25/09/09.

Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 1128 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, placed within the time frame of our inspection and testing programme between 23/02/09-18/05/09 and 26/06/09-20/08/09 is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty. Ltd. on 3881 3511.


A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L

Enc. Drawing showing lateral extent of controlled filling
ab3476mb



**CIVIL
QUALITY
ASSURANCE
(QLD) PTY LTD**
ABN 52 058 865 431

GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON – HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LAIDLEY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
laidley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09G

25 September 2009
Job No. CQA/09/191

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4001

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 115 – BALANCE OF WORKS
REAL PROPERTY DESCRIPTION:
LOT NO. 904 ON SP206021, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 1130

Fill was placed on this lot during the construction of this estate.

Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/09/191 dated 25/09/09.

Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 1130 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, placed within the time frame of our inspection and testing programme between 23/02/09-18/05/09 and 26/06/09-20/08/09 is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty. Ltd. on 3881 3511.


A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L

Enc. Drawing showing lateral extent of controlled filling
ab3476mb



**CIVIL
QUALITY
ASSURANCE
(QLD) PTY LTD**
ABN 52 058 865 431

GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON – HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LAIDLEY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
laidley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09G

25 September 2009
Job No. CQA/09/191

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4001

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 115 – BALANCE OF WORKS
REAL PROPERTY DESCRIPTION:
LOT NO. 904 ON SP206021, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 1131

Fill was placed on this lot during the construction of this estate.

Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/09/191 dated 25/09/09.

Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 1131 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, placed within the time frame of our inspection and testing programme between 23/02/09-18/05/09 and 26/06/09-20/08/09 is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty. Ltd. on 3881 3511.



A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L

Enc. Drawing showing lateral extent of controlled filling
ab3476mb



**CIVIL
QUALITY
ASSURANCE
(QLD) PTY LTD**
ABN 62 058 865 431

GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON – HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LIDLAY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
laidley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09G

25 September 2009
Job No. CQA/09/191

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4001

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 115 – BALANCE OF WORKS
REAL PROPERTY DESCRIPTION:
LOT NO. 904 ON SP206021, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 1132

Fill was placed on this lot during the construction of this estate.

Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/09/191 dated 25/09/09.

Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 1132 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, placed within the time frame of our inspection and testing programme between 23/02/09-18/05/09 and 26/06/09-20/08/09 is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty. Ltd. on 3881 3511.



A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L

Enc. Drawing showing lateral extent of controlled filling
ab3476mb



**CIVIL
QUALITY
ASSURANCE
(QLD) PTY LTD**
ABN 52 058 855 431

**GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS**

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON – HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LAIDLEY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
laidley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09G

25 September 2009
Job No. CQA/09/191

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4001

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 115 – BALANCE OF WORKS
REAL PROPERTY DESCRIPTION:
LOT NO. 904 ON SP206021, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 1133

Fill was placed on this lot during the construction of this estate.

Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/09/191 dated 25/09/09.

Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 1133 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, placed within the time frame of our inspection and testing programme between 23/02/09-18/05/09 and 26/06/09-20/08/09 is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.


Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty. Ltd. on 3881 3511.



A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L

Enc. Drawing showing lateral extent of controlled filling
ab3476mb



**CIVIL
QUALITY
ASSURANCE
(QLD) PTY LTD**
ABN 52 058 855 431

GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON – HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LAIDLEY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
laidley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09G

25 September 2009
Job No. CQA/09/191

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4001

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 115 – BALANCE OF WORKS
REAL PROPERTY DESCRIPTION:
LOT NO. 904 ON SP206021, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 1134

Fill was placed on this lot during the construction of this estate.

Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/09/191 dated 25/09/09.

Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 1134 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, placed within the time frame of our inspection and testing programme between 23/02/09-18/05/09 and 26/06/09-20/08/09 is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.


Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty. Ltd. on 3881 3511.



A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L

Enc. Drawing showing lateral extent of controlled filling
ab3476mb



**CIVIL
QUALITY
ASSURANCE
(QLD) PTY LTD**
ABN 52 058 855 431

GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON – HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LAIDLEY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
laidley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09G

25 September 2009
Job No. CQA/09/191

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4001

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 115 – BALANCE OF WORKS
REAL PROPERTY DESCRIPTION:
LOT NO. 904 ON SP206021, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 1135

Fill was placed on this lot during the construction of this estate.

Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/09/191 dated 25/09/09.

Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 1135 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, placed within the time frame of our inspection and testing programme between 23/02/09-18/05/09 and 26/06/09-20/08/09 is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty. Ltd. on 3881 3511.



**A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L**

Enc. Drawing showing lateral extent of controlled filling
ab3476mb



**CIVIL
QUALITY
ASSURANCE
(QLD) PTY LTD**
ABN 52 058 855 431

GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON – HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LAILLEY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
laidley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09G

25 September 2009
Job No. CQA/09/191

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4001

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 115 – BALANCE OF WORKS
REAL PROPERTY DESCRIPTION:
LOT NO. 904 ON SP206021, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 1136

Fill was placed on this lot during the construction of this estate.

Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/09/191 dated 25/09/09.

Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 1136 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, placed within the time frame of our inspection and testing programme between 23/02/09-18/05/09 and 26/06/09-20/08/09 is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty. Ltd. on 3881 3511.



A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L

Enc. Drawing showing lateral extent of controlled filling
ab3476mb



**CIVIL
QUALITY
ASSURANCE
(QLD) PTY LTD**
ABN 52 056 855 431

GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON – HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LAIDLEY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
laidley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09G

25 September 2009
Job No. CQA/09/191

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4001

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 115 – BALANCE OF WORKS
REAL PROPERTY DESCRIPTION:
LOT NO. 904 ON SP206021, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 1137

Fill was placed on this lot during the construction of this estate.

Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/09/191 dated 25/09/09.

Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 1137 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, placed within the time frame of our inspection and testing programme between 23/02/09-18/05/09 and 26/06/09-20/08/09 is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty. Ltd. on 3881 3511.



A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L

Enc. Drawing showing lateral extent of controlled filling
ab3476mb



**CIVIL
QUALITY
ASSURANCE
(QLD) PTY LTD**
ABN 52 058 855 431

**GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS**

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON – HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3533
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LAIDLEY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
laidley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09G

25 September 2009
Job No. CQA/09/191

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4001

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 115 – BALANCE OF WORKS
REAL PROPERTY DESCRIPTION:
LOT NO. 904 ON SP206021, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 1138

Fill was placed on this lot during the construction of this estate.

Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/09/191 dated 25/09/09.

Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 1138 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, placed within the time frame of our inspection and testing programme between 23/02/09-18/05/09 and 26/06/09-20/08/09 is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.


Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty. Ltd. on 3881 3511.



A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L

Enc. Drawing showing lateral extent of controlled filling
ab3476mb



**CIVIL
QUALITY
ASSURANCE**
(QLD) PTY LTD
ABN 52 058 855 431

GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON – HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LAIDLEY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
laidley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09G

25 September 2009
Job No. CQA/09/191

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4001

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 115 – BALANCE OF WORKS
REAL PROPERTY DESCRIPTION:
LOT NO. 904 ON SP206021, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 1139

Fill was placed on this lot during the construction of this estate.

Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/09/191 dated 25/09/09.

Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 1139 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, placed within the time frame of our inspection and testing programme between 23/02/09-18/05/09 and 26/06/09-20/08/09 is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.


Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty. Ltd. on 3881 3511.



**A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L**

Enc. Drawing showing lateral extent of controlled filling
ab3476mb



**CIVIL
QUALITY
ASSURANCE
(QLD) PTY LTD**

ABN 52 058 865 431

**GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS**

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON – HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LAIDLEY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
laidley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09G

25 September 2009
Job No. CQA/09/191

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4001

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 115 – BALANCE OF WORKS
REAL PROPERTY DESCRIPTION:
LOT NO. 904 ON SP206021, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 1140

Fill was placed on this lot during the construction of this estate.

Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/09/191 dated 25/09/09.

Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 1140 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, placed within the time frame of our inspection and testing programme between 23/02/09-18/05/09 and 26/06/09-20/08/09 is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty. Ltd. on 3881 3511.



A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L

Enc. Drawing showing lateral extent of controlled filling
ab3476mb



**CIVIL
QUALITY
ASSURANCE
(QLD) PTY LTD**
ABN 52 058 855 431

GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON – HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LAILY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
laily@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09G

25 September 2009
Job No. CQA/09/191

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4001

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 115 – BALANCE OF WORKS
REAL PROPERTY DESCRIPTION:
LOT NO. 904 ON SP206021, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 1141

Fill was placed on this lot during the construction of this estate.

Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/09/191 dated 25/09/09.

Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 1141 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, placed within the time frame of our inspection and testing programme between 23/02/09-18/05/09 and 26/06/09-20/08/09 is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty. Ltd. on 3881 3511.



**A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L**

Enc. Drawing showing lateral extent of controlled filling
ab3476mb



**CIVIL
QUALITY
ASSURANCE
(QLD) PTY LTD**
ABN 52 058 865 431

GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON – HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LAIDLEY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
laidley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09G

25 September 2009
Job No. CQA/09/191

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4001

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 115 – BALANCE OF WORKS
REAL PROPERTY DESCRIPTION:
LOT NO. 904 ON SP206021, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 1147

Fill was placed on this lot during the construction of this estate.

Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/09/191 dated 25/09/09.

Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 1147 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, placed within the time frame of our inspection and testing programme between 23/02/09-18/05/09 and 26/06/09-20/08/09 is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty. Ltd. on 3881 3511.



A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L

Enc. Drawing showing lateral extent of controlled filling
ab3476mb



**CIVIL
QUALITY
ASSURANCE
(QLD) PTY LTD**
ABN 52 058 855 431

GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON – HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LIDLAY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
laidley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09G

25 September 2009
Job No. CQA/09/191

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4001

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 115 – BALANCE OF WORKS
REAL PROPERTY DESCRIPTION:
LOT NO. 904 ON SP206021, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 1148

Fill was placed on this lot during the construction of this estate.

Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/09/191 dated 25/09/09.

Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 1148 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, placed within the time frame of our inspection and testing programme between 23/02/09-18/05/09 and 26/06/09-20/08/09 is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.


Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty. Ltd. on 3881 3511.



A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L

Enc. Drawing showing lateral extent of controlled filling
ab3476mb



**CIVIL
QUALITY
ASSURANCE
(QLD) PTY LTD**
ABN 62 058 855 431

GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON – HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LIDLAY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
laidley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09G

25 September 2009
Job No. CQA/09/191

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4001

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 115 – BALANCE OF WORKS
REAL PROPERTY DESCRIPTION:
LOT NO. 904 ON SP206021, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 1149

Fill was placed on this lot during the construction of this estate.

Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/09/191 dated 25/09/09.

Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 1149 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, placed within the time frame of our inspection and testing programme between 23/02/09-18/05/09 and 26/06/09-20/08/09 is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.


Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty. Ltd. on 3881 3511.



A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L

Enc. Drawing showing lateral extent of controlled filling
ab3476mb



**CIVIL
QUALITY
ASSURANCE
(QLD) PTY LTD**
ABN 52 058 855 431

GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON – HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LAIDLEY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
laidley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09G

25 September 2009
Job No. CQA/09/191

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4001

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 115 – BALANCE OF WORKS
REAL PROPERTY DESCRIPTION:
LOT NO. 904 ON SP206021, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 1150

Fill was placed on this lot during the construction of this estate.

Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/09/191 dated 25/09/09.

Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 1150 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, placed within the time frame of our inspection and testing programme between 23/02/09-18/05/09 and 26/06/09-20/08/09 is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty. Ltd. on 3881 3511.



A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L

Enc. Drawing showing lateral extent of controlled filling
ab3476mb



**CIVIL
QUALITY
ASSURANCE**
(QLD) PTY LTD
ABN 52 058 855 431

GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON – HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LAILLEY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
laidley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09G

25 September 2009
Job No. CQA/09/191

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4001

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 115 – BALANCE OF WORKS
REAL PROPERTY DESCRIPTION:
LOT NO. 904 ON SP206021, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 1178

Fill was placed on this lot during the construction of this estate.

Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/09/191 dated 25/09/09.

Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 1178 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, placed within the time frame of our inspection and testing programme between 23/02/09-18/05/09 and 26/06/09-20/08/09 is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty. Ltd. on 3881 3511.



**A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L**

Enc. Drawing showing lateral extent of controlled filling
ab3476mb



**CIVIL
QUALITY
ASSURANCE
(QLD) PTY LTD**
ABN 52 058 855 431

GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON – HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LIDLAY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
laidley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09G

25 September 2009
Job No. CQA/09/191

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4001

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 115 – BALANCE OF WORKS
REAL PROPERTY DESCRIPTION:
LOT NO. 904 ON SP206021, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 1179

Fill was placed on this lot during the construction of this estate.

Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/09/191 dated 25/09/09.

Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 1179 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, placed within the time frame of our inspection and testing programme between 23/02/09-18/05/09 and 26/06/09-20/08/09 is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty. Ltd. on 3881 3511.



**A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L**

Enc. Drawing showing lateral extent of controlled filling
ab3476mb



**CIVIL
QUALITY
ASSURANCE
(QLD) PTY LTD**

ABN 52 058 855 431

**GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS**

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON – HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LADLEY OFFICE
43 VALUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
ladley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09G

25 September 2009
Job No. CQA/09/191

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4001

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 115 – BALANCE OF WORKS
REAL PROPERTY DESCRIPTION:
LOT NO. 904 ON SP206021, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 1180

Fill was placed on this lot during the construction of this estate.

Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/09/191 dated 25/09/09.

Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 1180 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, placed within the time frame of our inspection and testing programme between 23/02/09-18/05/09 and 26/06/09-20/08/09 is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty. Ltd. on 3881 3511.



**A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L**

Enc. Drawing showing lateral extent of controlled filling
ab3476mb



**CIVIL
QUALITY
ASSURANCE
(QLD) PTY LTD**
ABN 52 058 855 431

**GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS**

**ALL CORRESPONDENCE TO
PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON – HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LIDLAY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
laidley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09G

25 September 2009
Job No. CQA/09/191

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4001

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 115 – BALANCE OF WORKS
REAL PROPERTY DESCRIPTION:
LOT NO. 904 ON SP206021, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 1181

Fill was placed on this lot during the construction of this estate.

Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/09/191 dated 25/09/09.

Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 1181 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, placed within the time frame of our inspection and testing programme between 23/02/09-18/05/09 and 26/06/09-20/08/09 is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty. Ltd. on 3881 3511.



**A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L**

Enc. Drawing showing lateral extent of controlled filling
ab3476mb



**CIVIL
QUALITY
ASSURANCE
(QLD) PTY LTD**
ABN 52 058 855 431

GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON – HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LAIDLEY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
laidley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09G

25 September 2009
Job No. CQA/09/191

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4001

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 115 – BALANCE OF WORKS
REAL PROPERTY DESCRIPTION:
LOT NO. 904 ON SP206021, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 1182

Fill was placed on this lot during the construction of this estate.

Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/09/191 dated 25/09/09.

Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 1182 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, placed within the time frame of our inspection and testing programme between 23/02/09-18/05/09 and 26/06/09-20/08/09 is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.


Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty. Ltd. on 3881 3511.



A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L

Enc. Drawing showing lateral extent of controlled filling
ab3476mb



**CIVIL
QUALITY
ASSURANCE**
(QLD) PTY LTD
ABN 52 058 865 431

GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON – HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LAIDLEY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
laidley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09G

25 September 2009
Job No. CQA/09/191

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4001

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 115 – BALANCE OF WORKS
REAL PROPERTY DESCRIPTION:
LOT NO. 904 ON SP206021, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 1183

Fill was placed on this lot during the construction of this estate.

Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/09/191 dated 25/09/09.

Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 1183 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, placed within the time frame of our inspection and testing programme between 23/02/09-18/05/09 and 26/06/09-20/08/09 is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty. Ltd. on 3881 3511.



A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L

Enc. Drawing showing lateral extent of controlled filling
ab3476mb



**CIVIL
QUALITY
ASSURANCE
(QLD) PTY LTD**
ABN 52 056 855 431

GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON - HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LADLEY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
ladley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09G

25 September 2009
Job No. CQA/09/191

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4001

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 115 – BALANCE OF WORKS
REAL PROPERTY DESCRIPTION:
LOT NO. 904 ON SP206021, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 1184

Fill was placed on this lot during the construction of this estate.

Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/09/191 dated 25/09/09.

Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 1184 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, placed within the time frame of our inspection and testing programme between 23/02/09-18/05/09 and 26/06/09-20/08/09 is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty. Ltd. on 3881 3511.



A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L

Enc. Drawing showing lateral extent of controlled filling
ab3476mb



**CIVIL
QUALITY
ASSURANCE
(QLD) PTY LTD**
ABN 52 058 855 431

**GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS**

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON – HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LADLEY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
ladley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09G

25 September 2009
Job No. CQA/09/191

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4001

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 115 – BALANCE OF WORKS
REAL PROPERTY DESCRIPTION:
LOT NO. 904 ON SP206021, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 1185

Fill was placed on this lot during the construction of this estate.

Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/09/191 dated 25/09/09.

Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 1185 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, placed within the time frame of our inspection and testing programme between 23/02/09-18/05/09 and 26/06/09-20/08/09 is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty. Ltd. on 3881 3511.



A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L

Enc. Drawing showing lateral extent of controlled filling
ab3476mb



**CIVIL
QUALITY
ASSURANCE
(QLD) PTY LTD**
ABN 52 058 855 431

GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON – HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LADLEY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
ladley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09G

25 September 2009
Job No. CQA/09/191

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4001

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 115 – BALANCE OF WORKS
REAL PROPERTY DESCRIPTION:
LOT NO. 904 ON SP206021, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 1186

Fill was placed on this lot during the construction of this estate.

Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/09/191 dated 25/09/09.

Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 1186 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, placed within the time frame of our inspection and testing programme between 23/02/09-18/05/09 and 26/06/09-20/08/09 is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty. Ltd. on 3881 3511.



**A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L**

Enc. Drawing showing lateral extent of controlled filling
ab3476mb



**CIVIL
QUALITY
ASSURANCE
(QLD) PTY LTD**

ABN 52 058 865 431

**GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS**

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON – HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LAIDLEY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
laidley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09G

25 September 2009
Job No. CQA/09/191

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4001

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 115 – BALANCE OF WORKS
REAL PROPERTY DESCRIPTION:
LOT NO. 904 ON SP206021, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 1187

Fill was placed on this lot during the construction of this estate.

Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/09/191 dated 25/09/09.

Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 1187 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, placed within the time frame of our inspection and testing programme between 23/02/09-18/05/09 and 26/06/09-20/08/09 is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty. Ltd. on 3881 3511.


A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L

Enc. Drawing showing lateral extent of controlled filling
ab3476mb



**CIVIL
QUALITY
ASSURANCE
(QLD) PTY LTD**
ABN 52 058 855 431

GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON – HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LAIDLEY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
laidley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09G

25 September 2009
Job No. CQA/09/191

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4001

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 115 – BALANCE OF WORKS
REAL PROPERTY DESCRIPTION:
LOT NO. 904 ON SP206021, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 1188

Fill was placed on this lot during the construction of this estate.

Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/09/191 dated 25/09/09.

Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 1188 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, placed within the time frame of our inspection and testing programme between 23/02/09-18/05/09 and 26/06/09-20/08/09 is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty. Ltd. on 3881 3511.



**A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L**

Enc. Drawing showing lateral extent of controlled filling
ab3476mb



**CIVIL
QUALITY
ASSURANCE
(QLD) PTY LTD**

ABN 52 058 855 431

**GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS**

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON – HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LAILLEY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
lailley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"

FORM CQA/CF/09G

25 September 2009
Job No. CQA/09/191

Brown Consulting (Qld) Pty Ltd
PO Box 10349
Adelaide Street
BRISBANE QLD 4001

**RE: CERTIFICATE OF CONTROLLED FILLING:
WARNER LAKES ESTATE, STAGE 115 – BALANCE OF WORKS
REAL PROPERTY DESCRIPTION:
LOT NO. 904 ON SP206021, PARISH OF WARNER, COUNTY OF STANLEY**

LOT NO. 1189

Fill was placed on this lot during the construction of this estate.

Civil Quality Assurance (Qld) Pty Ltd (CQA) was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the CQA report (form CQA/CF/10), Job No. CQA/09/191 dated 25/09/09.

Based on the test results and site inspections, CQA concludes that the fill foundation to a depth of not less than 150mm and placement of compacted fill on Lot 1189 as defined laterally in the attached drawing is considered to comply with the requirements of Table 5.1 of AS 3798 and the project specification.

All fill in the areas defined in the attached drawing, placed within the time frame of our inspection and testing programme between 23/02/09-18/05/09 and 26/06/09-20/08/09 is considered to be "Controlled Fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.


Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

A full geotechnical site investigation/classification and foundation design for the specific ground conditions should be carried out by suitably qualified and experienced personnel, prior to building when the house type and location is known. This service can be provided if required, by contacting Civil Quality Assurance (Qld.) Pty. Ltd. on 3881 3511.



A BARCLAY
for and on behalf of
CIVIL QUALITY ASSURANCE (Q) P/L

Enc. Drawing showing lateral extent of controlled filling
ab3476mb



**CIVIL
QUALITY
ASSURANCE
(QLD) PTY LTD**

ABN 52 058 855 431

**GEOTECHNICAL
AND
ENVIRONMENTAL
CONSULTANTS**

ALL CORRESPONDENCE TO
**PO BOX 370
LAWNTON, QLD, 4501**

LAWNTON – HEAD OFFICE
1/18 LEANNE CRESCENT
PHONE (07) 3881 3511
FAX (07) 3881 3513
lawnton@cqa.com.au

LOGANHOLME OFFICE
10/10 BABDOYLE STREET
PHONE (07) 3801 3233
FAX (07) 3801 3633
logan@cqa.com.au

KUNDA PARK OFFICE
2/74 ENTERPRISE STREET
PHONE (07) 5450 1735
FAX (07) 5450 1535
kunda@cqa.com.au

LIDLAY OFFICE
43 VAUX STREET
PHONE (07) 5465 2955
FAX (07) 5465 2799
laidley@cqa.com.au

MALENY OFFICE
154 ENGLE ROAD
PHONE (07) 5429 6882
FAX (07) 5429 6882



"SERVING
QUEENSLAND
SINCE 1993"